

DIESSÉ DIAGNOSTICA SENESE SpA
53035 Monteriggioni (SI), Italy, Strada dei Laghi 39
Tel. +39 0577319554



QUALITY CONTROL CERTIFICATE

KIT NAME **88000-W19 WALL PELLITORY W19**

Code **88000-W19**

Lot No. **036**

2025-05

2024-06

REAGENTS

Label	Description	Lot.	Exp.	NO
D9931	88000-W19 WALL PELLITORY W19	036	2025-05	2X6
B9930	CALIBRATORE 88000-W19 WALL PELLITORY W19	036	2025-06	1
C9930	CONTROL SERUM 88000-W19 WALL PELLITORY W19	036	2025-06	1


CONTROLS

	Found results	Expected results
Calibrator (mOD)	300	≥ 100
Control Serum (KU/L)	10,7	6,6-15,0

CALIBRATOR

6 1 0 0 3 6 6 5 1 9 5 8 2 7 7 8 0 0

Label checked with barcode reader YES Operator Signature *RS*



CONTROL SERUM

6 1 0 0 3 6 6 2 7 5 0 0 0 0 0 0 0 1

Label checked with barcode reader YES Operator Signature *RS*



This batch has been manufactured and checked according to quality requirements. Hereby, it is released to distribution.

APPROVED RESPONSIBLE HEAD, Quality Control Reagents..... *RS*

DATE *05/06/2024*

WARNING: POTENTIAL BIOHAZARDOUS MATERIAL!

This kit may contain some reagents made with human serum or plasma. All serum or plasma used has been tested and found non-reactive for HIV-1/2, HCV and HBsAg. Because no method can offer complete assurance that HIV-1/2, HCV, HBsAg or other infectious agents are absent, reagents should be handled with maximum attention.