### DIESSE DIAGNOSTICA SENESE SPA

53035 Monteriggioni (SI), Italy, Strada dei Laghi 39 Tel. +39 0577319554



# Code 86046 Lot No. 033 QUALITY CONTROL CERTIFICATE Mile 2024-05

## REAGENTS

oel	Description	Lot.	Ехр.	NO
D3312	CARDIOLIPIN-G	033	2025-05	6X6
B3312	CALIBRATORE CARDIOLIPIN-G	033	2025-05	1
C3312	CONTROL SERUM CARDIOLIPIN-G	033	2025-05	1

## CONTROLS

	THE PROPERTY OF THE PROPERTY OF THE PARTY OF
Found results	Expected results

Calibrator (mOD)	380	≥ 100
Control Serum (GPLU/mL)	35,9	21,9-41,3


CALIBRATOR

3 3 5 0 3 3 6 4 2 3 3 9 4 5 6 0 0 0

Label checked with barcode reader

YES Operator Signature







This batch has been manufactured and checked according to quality requirements. Hereby, it is released to distribution.

APPROVED RESPONSIBLE HEAD, Quality Control Reagents...

ts office

DS05.90.40

# WARNING: POTENTIAL BIOHAZARDOUS MATERIAL!

This kit may contain some reagents made with human serum or plasma. All serum or plasma used has been tested and found non-reactive for HIV-1/2, HCV and HBsAg. Because no method can offer complete assurance that HIV-1/2, HCV, HBsAg or other infectious agents are absent, reagents should be handled with maximum attention.